

CUTTING DATA RECOMMENDATIONS

Uddeholm MIRRAX 40

Machining data are always dependent on the actual operation, the machine tool and the cutting data used. The machining data given in this datasheet are general guidelines that may have to be adjusted to the actual conditions of a specific machining operation.

